
Unmounting Aluminium pulley with countersunk screw



Scale

Sheet

1 of 1

Format

Disassembly process

- 1. Make sure to cover all oil and air holes in S/C
- 2. Place S/C with pulley up
- 3. Remove sticker
- 4. Secure pulley with hand
- 5. Drill a hole in the top of the screw with a 9,5mm drill, until the head comes off
- 6. This will not ruin the pulley
- 7. Replace with new DIN 7991 M10x25

